ICHL-015-OC16 build instructions

1. cut
Label each board and cut its pieces in the cuts.csv sequence. Tools: saw, tape measure.

2. layout
Lay out the stud left edges from the left reference face at 0, 16, 32, 46.5 inches. Tools: square, tape measure.

3. join-studs
Attach studs to the bottom and first top plate. Hardware schedule pending review.

4. cap
Attach the second top plate. Hardware schedule pending review.

5. inspect
Record the four measurements in qc.json. Tools: square, tape measure.